



Electrical Solutions Corporation

2368 Eastman Ave, Suite 13, Ventura, CA 93003
(805) 658-0848 ~ (805) 658-0868

SCADAAlarm 6.0 and Modem Setup with InTouch 9.0 sp1

SCADAAlarm phone number: (310) xxx-xxxx

Modem: Multi Tech 56k Data Fax Voice Modem, MT 5600 ZDXV

Support: Brian or John at Standard Automation (888) 334-3293, 8-6 central time,
or through email: support@mtlmost.com

Paging Company: Dial Page, (805) 966-4151

Pager information provided by Dial Page:

Access Number: 1-805-xxx-xxxx

Pager #1 Alpha Pager ID: xxxxxxxx

Pager #2 Alpha Pager ID: xxxxxxxx

Pager #1 Numeric Phone Number: (310) xxx-xxxx

Pager #2 Numeric Phone Number: (310) xxx-xxxx

Modem information provided by Dial Page:

Baud: 300

Data Bits: 7

Stop Bits: 2

Parity: even

Modem Driver information guessed at by programmer:

Modulation: Std

Protocol: Standard EC

Compression: Enabled

Flow Control: none

Location of configuration file: C:\Documents and Settings\All Users\Application
Data\Wonderware\SCADAAlarm\SCADAAlrm.ini

This file should include the following line:

Pager Service Comm (RateParityBits)=300e7